


Attention !

Measuring cables IWK-VS3a

Free end of cable: designation of the wires



Marking „1-One“
(Begin or Phase)

For all other versions: black is always zero